

UREATOP SW is 2 component aliphatic polyurethane topcoat for UREASPRAY SYSTEMS.

## APPLICATION

- Ensures colour stability of surfaces exposed to UV radiation (roofs, showrooms, parking decks, ...).
- For coating, pools and ponds exposed to outdoor conditions and aggressive reagents such as chlorine in swimming pools.

## ADVANTAGES

Cold applied system, easy application.

## APPLICATION PRESCRIPTIONS

- **Preparation**  
Thoroughly clean the surface to be treated in order to have a good adhesion. All dust, fat and loose particles are to be removed.
- **UREATOP SW**  
UREATOP SW can be applied with a brush, roll, airless and pneumatic paint gun. (Airless and gun: 120 bar, aperture 015). The elastic aliphatic topcoat UREATOP SW can be applied immediately after applying the urea spray. It is advisable to first clean the UREASPRAY with a solvent before applying the UREATOP SW.

## TECHNICAL DATA

<b>Pot life</b>	4 hours at room temperature
<b>Colour</b>	Deliverable in most RAL-colours
<b>Density</b>	± 1,2 kg/litre, colour dependant
<b>Flame point</b>	> 21°C
<b>Minimal working temperature</b>	Minimum +5°C underground temperature, minimum 3°C above thawing point
<b>Tack free</b>	After 1 hour
<b>Curing time</b>	Minimum 8 hours
<b>Second layer</b>	Wait minimum 18 hours
<b>Elasticity</b>	Keeps elasticity, even at low temperatures
<b>Adhesion</b>	Has good adhesion on several surfaces (coatings, plastics, ...)
<b>Gloss</b>	Conserves gloss (60 à 70% - 60° Gardner)

## USAGE

80 to 100 g/m<sup>2</sup> for a thickness of 50 microns (dry film).

## PACKAGING

Standard packaging:

- set 5 kg (4,4 kg component A + 0,6 kg component B)
- set 20 kg (17,6 kg component A + 2,4 kg component B)

## STORAGE

Store for 12 months in the original packaging. Keep the original packaging tightly closed to prevent contamination by humidity. Store in a dry place at a temperature between 10 and 30 °C.

## SAFETY AND HEALTH PRECAUTIONS

Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.

Use explosion-proof electrical/ventilating/lighting/equipment.

Do not breathe dust/fume/gas/mist/vapours/spray.

If on skin or hair: Take off immediately all contaminated clothing. Rinse skin with water/shower.

For more information, consult the safety data sheet.